

**Flood Control Project Maintenance
Levee Inspections**

2016 Channel Summary Report

Overall Unit and Item Ratings

Placer County

Truckee River

Overall Unit Rating	Rated Item	Item Rating
A	Vegetation & Obstructions	A
	Shoaling / Sedimentation	A
	Erosion / Bank Caving	A
	Revetments & Other Structural Appurtenances	A
	Encroachments	A

Flood Control Project Maintenance**Unit Cover Sheet****2016 Channel Inspection Results****Placer County**

Channel
Truckee River

Channel Rating	A
Date of Inspection	7/8/2016
DWR Inspector	Jai Lor
Accompanied By	

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Outlet Structure / Up

Rating **	A	Issue No.	1	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH_2016_NA0045_13_1_20160721_00021.jpg



View of the Truckee River looking upstream from the outlet structure towards Lake Tahoe. Summer 2016.

Rating **	A	Issue No.	1 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_1			

Photo 2 of 2 : CH_2016_NA0045_13_1_20160620_00001.jpg



Looking upstream from the outlet structure. Summer 2015.

Rating **	A	Issue No.	2	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_2			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Outlet Structure / Up (cont)

Rating **	A	Issue No.	3	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_3			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	4	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_4			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	5	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_5			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Outlet Structure / Down

Rating **	A	Issue No.	6	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_6			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH_2016_NA0045_13_6_20160721_00022.jpg



View of the river looking downstream from the outlet structure towards Highway 89. Summer 2016.

Rating **	A	Issue No.	6 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_6			

Photo 2 of 2 : CH_2016_NA0045_13_6_20160620_00004.jpg



Looking downstream from the outlet structure. Summer 2015.

Rating **	A	Issue No.	7	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_7			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Outlet Structure / Down (cont)

Rating **	A	Issue No.	8	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_8			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	9	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101°
Category	Rivers, Channels & Designated Flood			-120.144002°
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_9			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	10	GPS Lat/Long
Issue Type +	Ma	Location *		39.167101 °
Category	Rivers, Channels & Designated Flood			-120.144002 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_10			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Hwy 89 / Up

Rating **	A	Issue No.	11	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			
Action/Comments				
Inspector Comments: The flow going out the control structure is very low. Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH_2016_NA0045_13_11_20160721_00023.jpg



View of the river from Highway 89 looking upstream towards the outlet structure. Summer 2016.

Rating **	A	Issue No.	11 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_11			

Photo 2 of 2 : CH_2016_NA0045_13_11_20160620_00007.jpg



Looking upstream from Highway 89. Summer 2015.

Rating **	A	Issue No.	12	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_12			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View				
Hwy 89 / Up (cont)				
Rating **	A	Issue No.	13	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845°
Category	Rivers, Channels & Designated Flood			-120.144424°
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_13			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	A	Issue No.	14	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_14			
Action/Comments				
Inspector Comments: Existing riprap protection is properly maintained and is undamaged. Riprap clearly visible. Monitor scouring revetment on the slope of the left bank.				

Photo 1 of 1 : CH_2016_NA0045_13_14_20160721_00024.jpg



Revetments are starting to show signs of scouring. Monitor revetments. Summer 2016.

Rating **	A	Issue No.	15	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_15			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Hwy 89 / Down

Rating **	A	Issue No.	16	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_16			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Rating **	A	Issue No.	16 (cont)	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_16			

Photo 1 of 2 : CH_2016_NA0045_13_16_20160721_00025.jpg



View of the river looking downstream from Highway. Summer 2016.

Photo 2 of 2 : CH_2016_NA0045_13_16_20160620_00009.jpg



Looking downstream from Highway 89. Summer 2015.

Rating **	A	Issue No.	17	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_17			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View				
Hwy 89 / Down (cont)				
Rating **	A	Issue No.	18	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_18			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

No Photos

Rating **	N	Issue No.	19	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_19			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

No Photos

Rating **	A	Issue No.	20	GPS Lat/Long
Issue Type +	Ma	Location *		39.166845 °
Category	Rivers, Channels & Designated Flood			-120.144424 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_20			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

bike bridge / Up

Rating **	A	Issue No.	21	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_21			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH_2016_NA0045_13_21_20160721_00026.jpg



View of the river looking upstream from the bike bridge. Summer 2016.

Photo 2 of 2 : CH_2016_NA0045_13_21_20160620_00011.jpg



Looking upstream from the bike bridge. Summer 2015.

Rating **	A	Issue No.	22	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_22			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

bike bridge / Up (cont)

Rating **	A	Issue No.	23	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c _ 2012_23			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	24	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_24			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	25	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_25			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

bike bridge / Down

Rating **	A	Issue No.	26	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_26			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH_2016_NA0045_13_26_20160721_00027.jpg



View of the river looking down from the bike bridge. Summer 2016.

Photo 2 of 2 : CH_2016_NA0045_13_26_20160620_00013.jpg



Looking downstream from the bike bridge. Summer 2015.

Rating **	A	Issue No.	27	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_27			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

* Location
LS : Land Side
WS : Water Side
CR : Crown

** Rating
A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

bike bridge / Down (cont)

Rating **	A	Issue No.	28	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_28			

Action/Comments

Inspector Comments: No head cutting or horizontal deviation observed.

No Photos

Rating **	N	Issue No.	29	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_29			

Action/Comments

Inspector Comments: This item does not apply to this inspection.

No Photos

Rating **	A	Issue No.	30	GPS Lat/Long
Issue Type +	Ma	Location *		39.165170 °
Category	Rivers, Channels & Designated Flood			-120.147590 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_30			

Action/Comments

Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Tahoe City lumber yard / Up

Rating **	A	Issue No.	31	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_31			
Action/Comments				
Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.				

Photo 1 of 2 : CH_2016_NA0045_13_31_20160721_00028.jpg



View of the river looking upstream from Tahoe City Lumber Yard (36.162499, -120.151878). Summer 2016.

Photo 2 of 2 : CH_2016_NA0045_13_31_20160721_00029.jpg



View of the river looking upstream from Tahoe City Lumber Yard (39.162564, -120.153385). Summer 2016.

Rating **	A	Issue No.	32	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_32			
Action/Comments				
Inspector Comments: No shoaling or sedimentation present.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View				
Tahoe City lumber yard / Up (cont)				
Rating **	A	Issue No.	33	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_33			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	34	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_34			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	35	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_35			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Tahoe City lumber yard / Down

Rating **	A	Issue No.	36	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Vegetation & Obstructions			
DWR ID	DWR_NA0045_13_c_2012_36			

Action/Comments

Inspector Comments: Minimal, scattered obstructions or vegetation. The flow is not impeded.

Photo 1 of 2 : CH_2016_NA0045_13_36_20160721_00030.jpg



View of the river looking downstream from Tahoe City Lumber Yard (36.162499, -120.151878). Summer 2016.

Photo 2 of 2 : CH_2016_NA0045_13_36_20160721_00031.jpg



View of the river looking downstream from Tahoe City Lumber Yard (39.162564, -120.153385). Summer 2016.

Rating **	A	Issue No.	37	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Shoaling / Sedimentation			
DWR ID	DWR_NA0045_13_c_2012_37			

Action/Comments

Inspector Comments: No shoaling or sedimentation present.

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Channel 2016

Placer County

Channel	Channel Length	Inspection Start/End	Inspector
Truckee River	0.60	07/08/2016 07/08/2016	Jai Lor

Check Point / View

Tahoe City lumber yard / Down (cont)

Rating **	A	Issue No.	38	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Erosion / Bank Caving			
DWR ID	DWR_NA0045_13_c_2012_38			
Action/Comments				
Inspector Comments: No head cutting or horizontal deviation observed.				

No Photos

Rating **	N	Issue No.	39	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Revetments			
DWR ID	DWR_NA0045_13_c_2012_39			
Action/Comments				
Inspector Comments: This item does not apply to this inspection.				

No Photos

Rating **	A	Issue No.	40	GPS Lat/Long
Issue Type +	Ma	Location *		39.162480 °
Category	Rivers, Channels & Designated Flood			-120.151900 °
Item	Encroachments			
DWR ID	DWR_NA0045_13_c_2012_40			
Action/Comments				
Inspector Comments: No trash, debris, excavation, structures, or other obstructions present within the project easement area.				

No Photos

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement